



THE NEXT GENERATION IN LOCKING

Carbine CEL 3in1 Touchscreen Locks

CEL-RFID

TROUBLESHOOTING



Tried a samsung galaxy S5 and it wouldn't accept it.

Turned on android S beam (NFC) and Paywave and neither worked.

2 beeps but quicker and red lights

I received a call from a locksmith yesterday claiming that his new cel3in1 deadbolt had a fault.

He stated that the inside snib was clicking on the last 15 degrees of its turn (towards the unlocked position)

THIS IS NORMAL, this changes the handing I believe.

After the lock is installed it must be set so the inside snib is in the vertical position and when you lock it with the keypad (they have an initial calibration cycle the first time you lock it with the combo ie. 1-8)

The lock will then operate freely and smooth in its full 90 degree sweep.

**THE
NEXT
GENERATION
IN LOCKING**

**AUSTRALIA
HEAD OFFICE**
14 John Hines Avenue
Minchinbury NSW 2770
1300 722 311
sales@carbine.com.au